

“IPS TAKES THE HASSLE OUT OF SEALING INSPECTION PORTS WITH 5 EASY STEPS.”



STEP 1



CUT HOLE WITH HOLE SAW

STEP 2



REMOVE INSULATION

STEP 3



INSERT SEALING FLANGE

STEP 4



REPLACE INSULATION

STEP 5



INSERT CAP



“IPS SAVES YOU 15 MINUTES PER TML WITH OUR 5 STEP SYSTEM.”